

Class "A" Permits | Work Order Unit

Inspection Records for Permit Number A2025-001016

Job Address: 6309 W 77TH PL

APN: 4109002009

SR Number: 1-4917994071

> Inspection Record Number 1

Inspection Date:	07/28/2025
Inspector:	Ludwin Ortega
Inspection Type:	FINAL
Inspection Hours:	1.0
Record Date:	07/30/2025
Record Entered By:	Ludwin Ortega
Inspection Comments:	FINAL INSPECTION: THE WORK PERFORMED UNDER THIS A PERMIT IS COMPLIANT WITH THE REBATE ASSESSMENT, ADA REGULATIONS AND CITY SPECIFICATIONS. OK TO FINAL SITE AND RELEASE REBATE

